



### Einsatzhülsen für MK mit Lappen DIN 6383

Morse taper adaptor for flat tang

Douilles intermédiaires à cone morse



**Form AD**

**Form AD/B**

	SK	x	MK	x	A	D	L	Artikel-Nr.
<b>SK</b>	<b>30</b>	x	1	x	50	25	103	G360 30x1x 50
<b>30</b>	<b>30</b>	x	1	x	100	25	148	G360 30x1x100
			30	x	2	x	65	32
			30	x	2	x	100	32
			30	x	3	x	80	113
			30	x	3	x	80	148
			40	x	1	x	128	G360 30x3x 80
<b>SK</b>	<b>40</b>	x	1	x	50	25	119	G360 40x1x 50
<b>40</b>	<b>40</b>	x	2	x	50	32	119	G360 40x2x 50
			40	x	2	x	117	32
			40	x	2	x	150	186
			40	x	2	x	200	32
			40	x	3	x	70	219
			40	x	3	x	133	269
			40	x	3	x	200	139
			40	x	4	x	95	202
			40	x	4	x	156	269
			40	x	4	x	200	164
			40	x	4	x	200	226
			40	x	4	x	200	269
			40	x	4	x	200	G360 40x4x 95
			40	x	4	x	156	G360 40x4x156
			40	x	4	x	200	G360 40x4x200

	SK	x	MK	x	A	D	L	Artikel-Nr.
	<b>50</b>	x	1	x	<b>45</b>	25	147	G360 50x1x 45
<b>SK</b>	<b>50</b>	x	2	x	<b>50</b>	32	152	G360 50x2x 50
<b>50</b>	<b>50</b>	x	2	x	<b>117</b>	32	219	G360 50x2x117
	<b>50</b>	x	2	x	<b>150</b>	32	252	G360 50x2x150
	<b>50</b>	x	2	x	<b>200</b>	26	302	G360 50x2x200
	<b>50</b>	x	3	x	<b>65</b>	40	167	G360 50x3x 65
	<b>50</b>	x	3	x	<b>137</b>	40	239	G360 50x3x137
	<b>50</b>	x	3	x	<b>150</b>	33	252	G360 50x3x150
	<b>50</b>	x	4	x	<b>95</b>	48	197	G360 50x4x 95
	<b>50</b>	x	4	x	<b>167</b>	48	269	G360 50x4x167
	<b>50</b>	x	4	x	<b>200</b>	48	302	G360 50x4x200
	<b>50</b>	x	4	x	<b>300</b>	48	402	G360 50x4x300
	<b>50</b>	x	5	x	<b>105</b>	63	207	G360 50x5x105
	<b>50</b>	x	5	x	<b>200</b>	63	302	G360 50x5x200